WORK INSTRUCTION

Document ID: DOC-0000707
Project: PRJ-036
Uploaded on: 2023-10-08
Uploaded by: user102
Export class: EAR99

Assembly of P-100300 at plant PLT02

Part Number: P-100300
Revision: B.1
Plant: PLT02
Station: ST-46
Torque (Nm): 5
Cycle time (s): 42

Step 1: Move to next station

Step 2: Visual check

Step 3: Visual check

Step 4: Move to next station

Step 5: Clean mating surface

Step 6: Inspect incoming part

Step 7: Visual check