# WORK INSTRUCTION

**Document ID:** DOC-0000767
**Project:** PRJ-002
**Uploaded on:** 2023-11-09
**Uploaded by:** user171
**Export class:** EAR99

## Assembly of P-100931 at plant PLT01

**Part Number:** P-100931
**Revision:** A.1
**Plant:** PLT01
**Station:** ST-52
**Torque (Nm):** 20
**Cycle time (s):** 289

Step 1: Clean mating surface

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Torque to specification