WORK INSTRUCTION

Document ID: DOC-0000813
Project: PRJ-010
Uploaded on: 2023-11-28
Uploaded by: user149
Export class: EAR99

Assembly of P-100419 at plant PLT04

Part Number: P-100419
Revision: A.1
Plant: PLT04
Station: ST-30
Torque (Nm): 20
Cycle time (s): 99

Step 1: Record result

Step 2: Inspect incoming part

Step 3: Clean mating surface

Step 4: Visual check

Step 5: Visual check

Assembly of P-101127 at plant PLT03

Part Number: P-101127
Revision: A.1
Plant: PLT03
Station: ST-58
Torque (Nm): 8
Cycle time (s): 212

Step 1: Record result

Step 2: Fit fasteners

Step 3: Apply thread locker

Step 4: Move to next station

Step 5: Move to next station