WORK INSTRUCTION

Document ID: DOC-0000913
Project: PRJ-013
Uploaded on: 2024-01-29
Uploaded by: user156
Export class: EAR99

Assembly of P-100040 at plant PLT02

Part Number: P-100040
Revision: A.1
Plant: PLT02
Station: ST-94
Torque (Nm): 2.5
Cycle time (s): 119

Step 1: Inspect incoming part

Step 2: Inspect incoming part

Step 3: Record result

Step 4: Record result

Step 5: Apply thread locker