WORK INSTRUCTION

Document ID: DOC-0000943
Project: PRJ-004
Uploaded on: 2024-02-10
Uploaded by: user142
Export class: EAR99

Assembly of P-100229 at plant PLT04

Part Number: P-100229
Revision: B.1
Plant: PLT04
Station: ST-44
Torque (Nm): 2.5
Cycle time (s): 262

Step 1: Visual check

Step 2: Inspect incoming part

Step 3: Inspect incoming part

Step 4: Record result

Step 5: Apply thread locker

Step 6: Torque to specification

Step 7: Move to next station