WORK INSTRUCTION

Document ID: DOC-0000988
Project: PRJ-009
Uploaded on: 2024-03-01
Uploaded by: user039
Export class: EAR99

Assembly of P-100724 at plant PLT03

Part Number: P-100724
Revision: A.1
Plant: PLT03
Station: ST-39
Torque (Nm): 5
Cycle time (s): 226

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Clean mating surface

Step 6: Inspect incoming part

Step 7: Move to next station