WORK INSTRUCTION

Document ID:	DOC-0001019
Project:	PRJ-024
Uploaded on:	2024-03-16
Uploaded by:	user130
Export class:	EAR99

Assembly of P-100183 at plant PLT02

Part Number:	P-100183
Revision:	B.1
Plant:	PLT02
Station:	ST-75
Torque (Nm):	8
Cycle time (s):	190

Step 1: Record result

Step 2: Inspect incoming part

Step 3: Visual check

Step 4: Visual check

Step 5: Inspect incoming part

Step 6: Fit fasteners

Step 7: Fit fasteners

Step 8: Clean mating surface