WORK INSTRUCTION

Document ID: DOC-0001025
Project: PRJ-039
Uploaded on: 2024-03-18
Uploaded by: user056
Export class: EAR99

Assembly of P-101073 at plant PLT03

Part Number: P-101073
Revision: A.1
Plant: PLT03
Station: ST-71
Torque (Nm): 20
Cycle time (s): 69

Step 1: Inspect incoming part

Step 2: Clean mating surface

Step 3: Record result

Step 4: Record result

Step 5: Record result

Step 6: Record result