WORK INSTRUCTION

Document ID: DOC-0001155
Project: PRJ-027
Uploaded on: 2024-05-26
Uploaded by: user165
Export class: EAR99

Assembly of P-100289 at plant PLT04

Part Number: P-100289
Revision: A.1
Plant: PLT04
Station: ST-90
Torque (Nm): 5
Cycle time (s): 255

Step 1: Record result

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Inspect incoming part

Step 5: Torque to specification

Step 6: Visual check

Step 7: Apply thread locker

Assembly of P-100466 at plant PLT01

Part Number: P-100466
Revision: B.1
Plant: PLT01
Station: ST-32
Torque (Nm): 12
Cycle time (s): 173

Step 1: Move to next station

Step 2: Record result

Step 3: Inspect incoming part

Step 4: Move to next station

Step 5: Visual check

Step 6: Clean mating surface