WORK INSTRUCTION

Document ID: DOC-0001243
Project: PRJ-022
Uploaded on: 2024-07-02
Uploaded by: user147
Export class: EAR99

Assembly of P-100090 at plant PLT04

Part Number: P-100090
Revision: A.1
Plant: PLT04
Station: ST-49
Torque (Nm): 2.5
Cycle time (s): 285

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Visual check

Step 4: Torque to specification

Step 5: Visual check

Step 6: Torque to specification

Step 7: Apply thread locker