# WORK INSTRUCTION

**Document ID:** DOC-0001290
**Project:** PRJ-026
**Uploaded on:** 2024-07-23
**Uploaded by:** user011
**Export class:** EAR99

## Assembly of P-100799 at plant PLT04

**Part Number:** P-100799
**Revision:** A.1
**Plant:** PLT04
**Station:** ST-53
**Torque (Nm):** 5
**Cycle time (s):** 267

Step 1: Visual check

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Record result

Step 5: Record result

Step 6: Clean mating surface

Step 7: Visual check

Step 8: Fit fasteners

## Assembly of P-101357 at plant PLT04

**Part Number:** P-101357
**Revision:** A.1
**Plant:** PLT04
**Station:** ST-55
**Torque (Nm):** 20
**Cycle time (s):** 121

Step 1: Apply thread locker

Step 2: Record result

Step 3: Clean mating surface

Step 4: Move to next station

Step 5: Visual check

Step 6: Torque to specification

Step 7: Visual check