WORK INSTRUCTION

Document ID: DOC-0001419
Project: PRJ-023
Uploaded on: 2024-09-14
Uploaded by: user044
Export class: EAR99

Assembly of P-100407 at plant PLT04

Part Number: P-100407
Revision: A.1
Plant: PLT04
Station: ST-71
Torque (Nm): 20
Cycle time (s): 230

Step 1: Move to next station

Step 2: Visual check

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Torque to specification

Step 6: Torque to specification

Step 7: Fit fasteners