EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001475
Project: PRJ-038
Uploaded on: 2024-10-09
Uploaded by: user052
Export class: ECCN-3A001

Assembly of P-100045 at plant PLT02

Part Number: P-100045
Revision: A.1
Plant: PLT02
Station: ST-13
Torque (Nm): 8
Cycle time (s): 265

Step 1: Apply thread locker

Step 2: Inspect incoming part

Step 3: Visual check

Step 4: Record result

Step 5: Move to next station

Step 6: Visual check

Step 7: Clean mating surface