EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001484
Project: PRJ-002
Uploaded on: 2024-10-13
Uploaded by: user020
Export class: ECCN-3A001

Assembly of P-102374 at plant PLT03

Part Number: P-102374
Revision: A.1
Plant: PLT03
Station: ST-33
Torque (Nm): 20
Cycle time (s): 254

Step 1: Move to next station

Step 2: Apply thread locker

Step 3: Visual check

Step 4: Inspect incoming part

Step 5: Apply thread locker

Step 6: Apply thread locker

Step 7: Visual check

Step 8: Torque to specification