EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001505
Project: PRJ-034
Uploaded on: 2024-10-20
Uploaded by: user079
Export class: ECCN-3A001

Assembly of P-100449 at plant PLT02

Part Number: P-100449
Revision: B.1
Plant: PLT02
Station: ST-87
Torque (Nm): 20
Cycle time (s): 275

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Record result

Step 4: Record result

Step 5: Apply thread locker

Step 6: Apply thread locker

Step 7: Fit fasteners