WORK INSTRUCTION

Document ID:	DOC-0001555
Project:	PRJ-035
Uploaded on:	2024-11-12
Uploaded by:	user119
Export class:	EAR99

Assembly of P-101910 at plant PLT04

Part Number:	P-101910
Revision:	A.1
Plant:	PLT04
Station:	ST-39
Torque (Nm):	8
Cycle time (s):	39

Step 1: Apply thread locker

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Move to next station