EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001577
Project: PRJ-005
Uploaded on: 2024-11-23
Uploaded by: user177
Export class: ECCN-3A001

Assembly of P-100868 at plant PLT04

Part Number: P-100868
Revision: B.1
Plant: PLT04
Station: ST-48
Torque (Nm): 20
Cycle time (s): 126

Step 1: Clean mating surface

Step 2: Visual check

Step 3: Clean mating surface

Step 4: Apply thread locker

Step 5: Visual check

Step 6: Fit fasteners

Step 7: Torque to specification

Step 8: Move to next station