WORK INSTRUCTION

Document ID: DOC-0001590
Project: PRJ-025
Uploaded on: 2024-11-28
Uploaded by: user122
Export class: EAR99

Assembly of P-100395 at plant PLT02

Part Number: P-100395
Revision: A.1
Plant: PLT02
Station: ST-84
Torque (Nm): 8
Cycle time (s): 41

Step 1: Clean mating surface

Step 2: Clean mating surface

Step 3: Visual check

Step 4: Inspect incoming part

Step 5: Torque to specification

Assembly of P-101830 at plant PLT01

Part Number: P-101830
Revision: A.1
Plant: PLT01
Station: ST-70
Torque (Nm): 5
Cycle time (s): 83

Step 1: Inspect incoming part

Step 2: Clean mating surface

Step 3: Fit fasteners

Step 4: Move to next station

Step 5: Fit fasteners

Step 6: Fit fasteners

Assembly of P-100585 at plant PLT03

Part Number: P-100585
Revision: D.1
Plant: PLT03
Station: ST-24
Torque (Nm): 8
Cycle time (s): 162

Step 1: Fit fasteners

Step 2: Torque to specification

Step 3: Record result

Step 4: Record result

Step 5: Torque to specification

Step 6: Torque to specification