WORK INSTRUCTION

Document ID: DOC-0001598
Project: PRJ-003
Uploaded on: 2024-12-01
Uploaded by: user023
Export class: EAR99

Assembly of P-100756 at plant PLT02

Part Number: P-100756
Revision: A.1
Plant: PLT02
Station: ST-38
Torque (Nm): 20
Cycle time (s): 49

Step 1: Record result

Step 2: Record result

Step 3: Visual check

Step 4: Visual check

Step 5: Move to next station

Step 6: Move to next station

Step 7: Apply thread locker

Step 8: Inspect incoming part

Assembly of P-101192 at plant PLT01

Part Number: P-101192
Revision: A.1
Plant: PLT01
Station: ST-11
Torque (Nm): 12
Cycle time (s): 107

Step 1: Move to next station

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Apply thread locker

Step 6: Move to next station

Step 7: Record result

Step 8: Clean mating surface