WORK INSTRUCTION

Document ID:	DOC-0001659
Project:	PRJ-007
Uploaded on:	2025-01-04
Uploaded by:	user011
Export class:	EAR99

Assembly of P-100357 at plant PLT04

Part Number:	P-100357
Revision:	B.1
Plant:	PLT04
Station:	ST-86
Torque (Nm):	20
Cycle time (s):	56

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Visual check

Step 5: Inspect incoming part