EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001908
Project: PRJ-028
Uploaded on: 2025-05-06
Uploaded by: user080
Export class: ECCN-3A001

Assembly of P-101049 at plant PLT02

Part Number: P-101049
Revision: A.1
Plant: PLT02
Station: ST-79
Torque (Nm): 8
Cycle time (s): 157

Step 1: Visual check

Step 2: Fit fasteners

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Inspect incoming part

Step 6: Visual check

Step 7: Inspect incoming part

Step 8: Record result

Assembly of P-101536 at plant PLT03

Part Number: P-101536
Revision: A.1
Plant: PLT03
Station: ST-27
Torque (Nm): 2.5
Cycle time (s): 137

Step 1: Record result

Step 2: Record result

Step 3: Clean mating surface

Step 4: Torque to specification

Step 5: Visual check