WORK INSTRUCTION

Document ID: DOC-0002068
Project: PRJ-006
Uploaded on: 2025-07-12
Uploaded by: user011
Export class: EAR99

Assembly of P-100159 at plant PLT03

Part Number: P-100159
Revision: C.1
Plant: PLT03
Station: ST-28
Torque (Nm): 5
Cycle time (s): 184

Step 1: Inspect incoming part

Step 2: Record result

Step 3: Apply thread locker

Step 4: Move to next station

Step 5: Fit fasteners