ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0002202
Project: PRJ-031
Uploaded on: 2025-09-18
Uploaded by: user123
Export class: ITAR-USML-XIX

Assembly of P-102986 at plant PLT04

Part Number: P-102986
Revision: A.1
Plant: PLT04
Station: ST-49
Torque (Nm): 5
Cycle time (s): 267

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Clean mating surface

Step 4: Apply thread locker

Step 5: Record result

Step 6: Apply thread locker

Assembly of P-100609 at plant PLT03

Part Number: P-100609
Revision: A.1
Plant: PLT03
Station: ST-11
Torque (Nm): 5
Cycle time (s): 43

Step 1: Record result

Step 2: Record result

Step 3: Inspect incoming part

Step 4: Fit fasteners

Step 5: Visual check

Step 6: Record result