WORK INSTRUCTION

Document ID: DOC-0002261
Project: PRJ-037
Uploaded on: 2025-10-15
Uploaded by: user008
Export class: EAR99

Assembly of P-102783 at plant PLT04

Part Number: P-102783
Revision: A.1
Plant: PLT04
Station: ST-70
Torque (Nm): 2.5
Cycle time (s): 44

Step 1: Inspect incoming part

Step 2: Move to next station

Step 3: Fit fasteners

Step 4: Visual check

Step 5: Fit fasteners

Step 6: Record result

Assembly of P-100647 at plant PLT02

Part Number: P-100647
Revision: D.1
Plant: PLT02
Station: ST-62
Torque (Nm): 12
Cycle time (s): 94

Step 1: Apply thread locker

Step 2: Visual check

Step 3: Apply thread locker

Step 4: Clean mating surface

Step 5: Inspect incoming part

Step 6: Visual check