WORK INSTRUCTION

Document ID: DOC-0002311
Project: PRJ-038
Uploaded on: 2025-11-10
Uploaded by: user149
Export class: EAR99

Assembly of P-101280 at plant PLT04

Part Number: P-101280
Revision: B.1
Plant: PLT04
Station: ST-93
Torque (Nm): 5
Cycle time (s): 147

Step 1: Visual check

Step 2: Move to next station

Step 3: Record result

Step 4: Fit fasteners

Step 5: Clean mating surface