WORK INSTRUCTION

Document ID: DOC-0002337
Project: PRJ-008
Uploaded on: 2025-11-22
Uploaded by: user199
Export class: EAR99

Assembly of P-101447 at plant PLT01

Part Number: P-101447
Revision: A.1
Plant: PLT01
Station: ST-56
Torque (Nm): 8
Cycle time (s): 141

Step 1: Clean mating surface

Step 2: Visual check

Step 3: Visual check

Step 4: Torque to specification

Step 5: Record result