EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0002362
Project: PRJ-022
Uploaded on: 2025-12-03
Uploaded by: user019
Export class: ECCN-3A001

Assembly of P-103427 at plant PLT02

Part Number: P-103427
Revision: A.1
Plant: PLT02
Station: ST-75
Torque (Nm): 8
Cycle time (s): 113

Step 1: Move to next station

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Fit fasteners

Step 5: Inspect incoming part

Step 6: Inspect incoming part

Step 7: Record result

Step 8: Record result

Assembly of P-102415 at plant PLT02

Part Number: P-102415
Revision: A.1
Plant: PLT02
Station: ST-53
Torque (Nm): 2.5
Cycle time (s): 163

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Inspect incoming part

Step 4: Torque to specification

Step 5: Inspect incoming part

Step 6: Visual check

Step 7: Torque to specification

Assembly of P-101210 at plant PLT04

Part Number: P-101210
Revision: A.1

Plant:	PLT04
Station:	ST-80
Torque (Nm):	2.5
Cycle time (s):	92

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Fit fasteners

Step 4: Fit fasteners

Step 5: Record result

Step 6: Fit fasteners