WORK INSTRUCTION

Document ID: DOC-0002459
Project: PRJ-039
Uploaded on: 2026-01-18
Uploaded by: user073
Export class: EAR99

Assembly of P-103676 at plant PLT01

Part Number: P-103676
Revision: A.1
Plant: PLT01
Station: ST-60
Torque (Nm): 20
Cycle time (s): 296

Step 1: Record result

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Move to next station

Step 5: Inspect incoming part

Step 6: Inspect incoming part

Step 7: Torque to specification