WORK INSTRUCTION

Document ID: DOC-0002461
Project: PRJ-006
Uploaded on: 2026-01-18
Uploaded by: user145
Export class: EAR99

Assembly of P-101224 at plant PLT03

Part Number: P-101224
Revision: B.1
Plant: PLT03
Station: ST-47
Torque (Nm): 8
Cycle time (s): 207

Step 1: Record result

Step 2: Visual check

Step 3: Visual check

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Apply thread locker

Step 7: Move to next station

Step 8: Record result

Assembly of P-101662 at plant PLT04

Part Number: P-101662
Revision: A.1
Plant: PLT04
Station: ST-35
Torque (Nm): 20
Cycle time (s): 126

Step 1: Torque to specification

Step 2: Record result

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Visual check

Step 6: Move to next station

Step 7: Fit fasteners

Step 8: Fit fasteners