EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0002603
Project: PRJ-034
Uploaded on: 2026-03-22
Uploaded by: user139
Export class: ECCN-3A001

Assembly of P-103874 at plant PLT01

Part Number: P-103874
Revision: A.1
Plant: PLT01
Station: ST-63
Torque (Nm): 12
Cycle time (s): 79

Step 1: Torque to specification

Step 2: Record result

Step 3: Move to next station

Step 4: Record result

Step 5: Torque to specification

Step 6: Move to next station

Step 7: Clean mating surface

Assembly of P-102451 at plant PLT01

Part Number: P-102451
Revision: B.1
Plant: PLT01
Station: ST-87
Torque (Nm): 12
Cycle time (s): 61

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Clean mating surface

Step 4: Fit fasteners

Step 5: Fit fasteners

Step 6: Visual check

Step 7: Inspect incoming part

Assembly of P-103633 at plant PLT01

Part Number: P-103633
Revision: A.1
Plant: PLT01

Station:	ST-68
Torque (Nm):	2.5
Cycle time (s):	251

Step 1: Record result

Step 2: Record result

Step 3: Fit fasteners

Step 4: Inspect incoming part

Step 5: Torque to specification

Step 6: Record result