WORK INSTRUCTION

Document ID: DOC-0002687
Project: PRJ-025
Uploaded on: 2026-05-02
Uploaded by: user054
Export class: EAR99

Assembly of P-102765 at plant PLT04

Part Number: P-102765
Revision: A.1
Plant: PLT04
Station: ST-35
Torque (Nm): 20
Cycle time (s): 227

Step 1: Record result

Step 2: Torque to specification

Step 3: Inspect incoming part

Step 4: Move to next station

Step 5: Clean mating surface

Step 6: Inspect incoming part

Assembly of P-103757 at plant PLT03

Part Number: P-103757
Revision: A.1
Plant: PLT03
Station: ST-14
Torque (Nm): 8
Cycle time (s): 287

Step 1: Torque to specification

Step 2: Record result

Step 3: Apply thread locker

Step 4: Fit fasteners

Step 5: Visual check

Step 6: Torque to specification

Step 7: Apply thread locker

Assembly of P-104337 at plant PLT03

Part Number: P-104337
Revision: A.1
Plant: PLT03
Station: ST-36
Torque (Nm): 2.5
Cycle time (s): 192

Step 1: Clean mating surface

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Visual check

Step 5: Visual check