WORK INSTRUCTION

Document ID: DOC-0002730
Project: PRJ-025
Uploaded on: 2026-05-29
Uploaded by: user081
Export class: EAR99

Assembly of P-100680 at plant PLT02

Part Number: P-100680
Revision: A.1
Plant: PLT02
Station: ST-71
Torque (Nm): 8
Cycle time (s): 231

Step 1: Torque to specification

Step 2: Record result

Step 3: Torque to specification

Step 4: Torque to specification

Step 5: Move to next station

Assembly of P-100272 at plant PLT01

Part Number: P-100272
Revision: B.1
Plant: PLT01
Station: ST-77
Torque (Nm): 8
Cycle time (s): 116

Step 1: Move to next station

Step 2: Move to next station

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Visual check

Step 6: Move to next station

Assembly of P-100903 at plant PLT03

Part Number: P-100903
Revision: B.1
Plant: PLT03
Station: ST-85
Torque (Nm): 2.5
Cycle time (s): 286

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Inspect incoming part

Step 5: Clean mating surface