ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0002748
Project: PRJ-029
Uploaded on: 2026-06-04
Uploaded by: user101
Export class: ITAR-USML-XIX

Assembly of P-101675 at plant PLT02

Part Number: P-101675
Revision: A.1
Plant: PLT02
Station: ST-90
Torque (Nm): 8
Cycle time (s): 193

Step 1: Move to next station

Step 2: Visual check

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Torque to specification

Assembly of P-101225 at plant PLT03

Part Number: P-101225
Revision: A.1
Plant: PLT03
Station: ST-71
Torque (Nm): 20
Cycle time (s): 233

Step 1: Torque to specification

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Visual check

Step 5: Move to next station

Step 6: Fit fasteners

Step 7: Inspect incoming part

Step 8: Clean mating surface

Assembly of P-103609 at plant PLT02

Part Number: P-103609
Revision: A.1
Plant: PLT02
Station: ST-50

Torque (Nm):	12
Cycle time (s):	88

Step 1: Clean mating surface

Step 2: Clean mating surface

Step 3: Record result

Step 4: Inspect incoming part

Step 5: Move to next station

Step 6: Visual check

Step 7: Inspect incoming part