WORK INSTRUCTION

Document ID: DOC-0002760
Project: PRJ-028
Uploaded on: 2026-06-10
Uploaded by: user039
Export class: EAR99

Assembly of P-104412 at plant PLT02

Part Number: P-104412
Revision: A.1
Plant: PLT02
Station: ST-70
Torque (Nm): 5
Cycle time (s): 225

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Clean mating surface

Step 4: Fit fasteners

Step 5: Move to next station

Step 6: Fit fasteners