WORK INSTRUCTION

Document ID: DOC-0002881
Project: PRJ-026
Uploaded on: 2026-08-03
Uploaded by: user084
Export class: EAR99

Assembly of P-100905 at plant PLT03

Part Number: P-100905
Revision: B.1
Plant: PLT03
Station: ST-53
Torque (Nm): 2.5
Cycle time (s): 210

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Visual check

Step 5: Clean mating surface

Step 6: Move to next station

Step 7: Inspect incoming part

Step 8: Visual check

Assembly of P-100015 at plant PLT03

Part Number: P-100015
Revision: E.1
Plant: PLT03
Station: ST-45
Torque (Nm): 5
Cycle time (s): 33

Step 1: Record result

Step 2: Fit fasteners

Step 3: Torque to specification

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Visual check

Assembly of P-102944 at plant PLT04

Part Number: P-102944
Revision: A.1
Plant: PLT04
Station: ST-17
Torque (Nm): 20

Cycle time (s): 208

Step 1: Apply thread locker

Step 2: Apply thread locker

Step 3: Visual check

Step 4: Move to next station

Step 5: Inspect incoming part

Step 6: Fit fasteners

Step 7: Move to next station

Step 8: Torque to specification