WORK INSTRUCTION

Document ID: DOC-0002944
Project: PRJ-035
Uploaded on: 2026-09-03
Uploaded by: user169
Export class: EAR99

Assembly of P-104482 at plant PLT02

Part Number: P-104482
Revision: A.1
Plant: PLT02
Station: ST-41
Torque (Nm): 5
Cycle time (s): 51

Step 1: Visual check

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Apply thread locker

Step 6: Visual check

Assembly of P-102221 at plant PLT03

Part Number: P-102221
Revision: A.1
Plant: PLT03
Station: ST-54
Torque (Nm): 20
Cycle time (s): 181

Step 1: Fit fasteners

Step 2: Torque to specification

Step 3: Inspect incoming part

Step 4: Move to next station

Step 5: Apply thread locker

Assembly of P-102063 at plant PLT01

Part Number: P-102063
Revision: A.1
Plant: PLT01
Station: ST-66
Torque (Nm): 12
Cycle time (s): 297

Step 1: Inspect incoming part

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Record result

Step 6: Fit fasteners