EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0002949
Project: PRJ-020
Uploaded on: 2026-09-12
Uploaded by: user189
Export class: ECCN-3A001

Assembly of P-101235 at plant PLT02

Part Number: P-101235
Revision: A.1
Plant: PLT02
Station: ST-36
Torque (Nm): 20
Cycle time (s): 109

Step 1: Fit fasteners

Step 2: Clean mating surface

Step 3: Fit fasteners

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Visual check

Step 7: Clean mating surface