ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0002950
Project: PRJ-025
Uploaded on: 2026-09-13
Uploaded by: user166
Export class: ITAR-USML-XIX

Assembly of P-103873 at plant PLT02

Part Number: P-103873
Revision: A.1
Plant: PLT02
Station: ST-16
Torque (Nm): 2.5
Cycle time (s): 293

Step 1: Move to next station

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Inspect incoming part

Step 5: Move to next station

Assembly of P-103838 at plant PLT01

Part Number: P-103838
Revision: A.1
Plant: PLT01
Station: ST-30
Torque (Nm): 20
Cycle time (s): 217

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Apply thread locker

Step 4: Visual check

Step 5: Inspect incoming part

Step 6: Move to next station

Assembly of P-100619 at plant PLT02

Part Number: P-100619
Revision: A.1
Plant: PLT02
Station: ST-89
Torque (Nm): 20
Cycle time (s): 127

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Record result

Step 4: Move to next station

Step 5: Torque to specification

Step 6: Fit fasteners