ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0002979
Project: PRJ-017
Uploaded on: 2026-09-26
Uploaded by: user182
Export class: ITAR-USML-XIX

Assembly of P-102883 at plant PLT01

Part Number: P-102883
Revision: A.1
Plant: PLT01
Station: ST-41
Torque (Nm): 2.5
Cycle time (s): 256

Step 1: Torque to specification

Step 2: Record result

Step 3: Clean mating surface

Step 4: Clean mating surface

Step 5: Apply thread locker

Step 6: Clean mating surface

Assembly of P-102651 at plant PLT03

Part Number: P-102651
Revision: A.1
Plant: PLT03
Station: ST-51
Torque (Nm): 8
Cycle time (s): 251

Step 1: Move to next station

Step 2: Record result

Step 3: Torque to specification

Step 4: Record result

Step 5: Fit fasteners

Step 6: Torque to specification