WORK INSTRUCTION

Document ID: DOC-0002995
Project: PRJ-003
Uploaded on: 2026-10-04
Uploaded by: user126
Export class: EAR99

Assembly of P-102836 at plant PLT02

Part Number: P-102836
Revision: B.1
Plant: PLT02
Station: ST-34
Torque (Nm): 8
Cycle time (s): 41

Step 1: Inspect incoming part

Step 2: Fit fasteners

Step 3: Clean mating surface

Step 4: Visual check

Step 5: Record result

Step 6: Apply thread locker

Step 7: Torque to specification