WORK INSTRUCTION

Document ID: DOC-0002999
Project: PRJ-035
Uploaded on: 2026-10-06
Uploaded by: user008
Export class: EAR99

Assembly of P-103776 at plant PLT02

Part Number: P-103776
Revision: A.1
Plant: PLT02
Station: ST-53
Torque (Nm): 2.5
Cycle time (s): 104

Step 1: Visual check

Step 2: Apply thread locker

Step 3: Torque to specification

Step 4: Apply thread locker

Step 5: Apply thread locker

Assembly of P-100240 at plant PLT02

Part Number: P-100240
Revision: A.1
Plant: PLT02
Station: ST-22
Torque (Nm): 2.5
Cycle time (s): 261

Step 1: Visual check

Step 2: Fit fasteners

Step 3: Fit fasteners

Step 4: Clean mating surface

Step 5: Torque to specification

Step 6: Move to next station

Assembly of P-101550 at plant PLT04

Part Number: P-101550
Revision: B.1
Plant: PLT04
Station: ST-56
Torque (Nm): 5
Cycle time (s): 52

Step 1: Record result

Step 2: Torque to specification

Step 3: Record result

Step 4: Torque to specification

Step 5: Inspect incoming part