WORK INSTRUCTION

Document ID: DOC-0000444
Project: PRJ-033
Uploaded on: 2023-06-01
Uploaded by: user017
Export class: EAR99

Assembly of P-100245 at plant PLT03

Part Number: P-100245
Revision: A.1
Plant: PLT03
Station: ST-10
Torque (Nm): 5
Cycle time (s): 285

Step 1: Move to next station

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Torque to specification

Step 6: Torque to specification

Step 7: Record result

Step 8: Inspect incoming part

Assembly of P-100231 at plant PLT03

Part Number: P-100231
Revision: A.1
Plant: PLT03
Station: ST-70
Torque (Nm): 5
Cycle time (s): 158

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Visual check

Step 6: Apply thread locker

Step 7: Apply thread locker