ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0001473
Project: PRJ-035
Uploaded on: 2024-10-07
Uploaded by: user163
Export class: ITAR-USML-XIX

Assembly of P-101004 at plant PLT03

Part Number: P-101004
Revision: A.1
Plant: PLT03
Station: ST-66
Torque (Nm): 2.5
Cycle time (s): 97

Step 1: Inspect incoming part

Step 2: Visual check

Step 3: Apply thread locker

Step 4: Visual check

Step 5: Fit fasteners

Step 6: Move to next station

Assembly of P-101878 at plant PLT02

Part Number: P-101878
Revision: A.1
Plant: PLT02
Station: ST-19
Torque (Nm): 12
Cycle time (s): 129

Step 1: Visual check

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Apply thread locker

Step 5: Inspect incoming part

Step 6: Inspect incoming part

Assembly of P-101768 at plant PLT01

Part Number: P-101768
Revision: A.1
Plant: PLT01
Station: ST-21
Torque (Nm): 5

Cycle time (s): 265

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Visual check

Step 4: Apply thread locker

Step 5: Record result

Step 6: Record result