# WORK INSTRUCTION

**Document ID:** DOC-0001509
**Project:** PRJ-001
**Uploaded on:** 2024-10-22
**Uploaded by:** user071
**Export class:** EAR99

## Assembly of P-101490 at plant PLT01

**Part Number:** P-101490
**Revision:** A.1
**Plant:** PLT01
**Station:** ST-97
**Torque (Nm):** 12
**Cycle time (s):** 294

Step 1: Clean mating surface

Step 2: Inspect incoming part

Step 3: Record result

Step 4: Clean mating surface

Step 5: Fit fasteners

## Assembly of P-100536 at plant PLT03

**Part Number:** P-100536
**Revision:** A.1
**Plant:** PLT03
**Station:** ST-53
**Torque (Nm):** 2.5
**Cycle time (s):** 203

Step 1: Fit fasteners

Step 2: Visual check

Step 3: Fit fasteners

Step 4: Torque to specification

Step 5: Fit fasteners

Step 6: Clean mating surface