WORK INSTRUCTION

Document ID: DOC-0001147
Project: PRJ-006
Uploaded on: 2024-05-22
Uploaded by: user060
Export class: EAR99

Assembly of P-100814 at plant PLT02

Part Number: P-100814
Revision: B.1
Plant: PLT02
Station: ST-24
Torque (Nm): 2.5
Cycle time (s): 249

Step 1: Record result

Step 2: Visual check

Step 3: Torque to specification

Step 4: Fit fasteners

Step 5: Record result

Step 6: Inspect incoming part

Step 7: Apply thread locker

Step 8: Visual check