WORK INSTRUCTION

Document ID: DOC-0001173
Project: PRJ-011
Uploaded on: 2024-06-01
Uploaded by: user163
Export class: EAR99

Assembly of P-100775 at plant PLT02

Part Number: P-100775
Revision: A.1
Plant: PLT02
Station: ST-99
Torque (Nm): 5
Cycle time (s): 50

Step 1: Visual check

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Visual check

Step 6: Apply thread locker

Assembly of P-100308 at plant PLT02

Part Number: P-100308
Revision: B.1
Plant: PLT02
Station: ST-23
Torque (Nm): 2.5
Cycle time (s): 268

Step 1: Record result

Step 2: Clean mating surface

Step 3: Record result

Step 4: Apply thread locker

Step 5: Move to next station

Assembly of P-101397 at plant PLT03

Part Number: P-101397
Revision: A.1
Plant: PLT03
Station: ST-49
Torque (Nm): 5
Cycle time (s): 62

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Apply thread locker

Step 6: Torque to specification

Step 7: Inspect incoming part