WORK INSTRUCTION

Document ID: DOC-0001190
Project: PRJ-036
Uploaded on: 2024-06-07
Uploaded by: user042
Export class: EAR99

Assembly of P-100135 at plant PLT01

Part Number: P-100135
Revision: B.1
Plant: PLT01
Station: ST-77
Torque (Nm): 12
Cycle time (s): 45

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Fit fasteners

Step 4: Inspect incoming part

Step 5: Visual check