WORK INSTRUCTION

Document ID: DOC-0000757
Project: PRJ-010
Uploaded on: 2023-11-02
Uploaded by: user108
Export class: EAR99

Assembly of P-100777 at plant PLT01

Part Number: P-100777
Revision: A.1
Plant: PLT01
Station: ST-13
Torque (Nm): 5
Cycle time (s): 91

Step 1: Apply thread locker

Step 2: Visual check

Step 3: Visual check

Step 4: Move to next station

Step 5: Apply thread locker

Step 6: Torque to specification

Step 7: Record result

Assembly of P-100484 at plant PLT01

Part Number: P-100484
Revision: A.1
Plant: PLT01
Station: ST-56
Torque (Nm): 5
Cycle time (s): 263

Step 1: Move to next station

Step 2: Move to next station

Step 3: Torque to specification

Step 4: Visual check

Step 5: Clean mating surface

Step 6: Torque to specification