TEST REPORT

Document ID: DOC-0000764
Project: PRJ-018
Uploaded on: 2023-11-07
Uploaded by: user115
Export class: EAR99

Report No: TR-937971
Laboratory: Lab South
Test Date: 2023-11-07

Part P-100964 rev A.1

Test	Requirement	Measured	Result
Hardness	20 - 60 HRC	33.725	PASS
Thermal cycle	50 - 500 cycles	70.597	PASS
Tensile strength	250 - 520 MPa	236.949	FAIL
Dimensional check	0.05 - 0.5 mm	0.308	PASS

Overall result for P-100964: FAIL

Part P-100477 rev B.1

Test	Requirement	Measured	Result
Tensile strength	250 - 520 MPa	249.677	FAIL
Hardness	20 - 60 HRC	22.832	PASS
Thermal cycle	50 - 500 cycles	373.404	PASS
Dimensional check	0.05 - 0.5 mm	0.397	PASS

Overall result for P-100477: FAIL

Part P-100874 rev A.1

Test	Requirement	Measured	Result
Hardness	20 - 60 HRC	46.644	PASS
Flatness	0.01 - 0.2 mm	0.173	PASS
Dimensional check	0.05 - 0.5 mm	0.539	FAIL
Tensile strength	250 - 520 MPa	522.349	FAIL

Overall result for P-100874: FAIL