WORK INSTRUCTION

Document ID: DOC-0000766
Project: PRJ-014
Uploaded on: 2023-11-09
Uploaded by: user125
Export class: EAR99

Assembly of P-100606 at plant PLT02

Part Number: P-100606
Revision: A.1
Plant: PLT02
Station: ST-54
Torque (Nm): 12
Cycle time (s): 184

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Record result

Step 4: Clean mating surface

Step 5: Move to next station

Step 6: Torque to specification

Step 7: Move to next station

Assembly of P-100612 at plant PLT02

Part Number: P-100612
Revision: A.1
Plant: PLT02
Station: ST-25
Torque (Nm): 20
Cycle time (s): 213

Step 1: Record result

Step 2: Apply thread locker

Step 3: Clean mating surface

Step 4: Fit fasteners

Step 5: Fit fasteners

Step 6: Move to next station